



 **CROC**[®]
ForkCoating

A Croc that won't take a
“Bite” out of your budget!

The CROC-Team in action in the recycling sector

The problem: frequent damages when loading aluminum coils

The slippery surface of the forks causes the aluminum coils to easily slide off when the lift truck brakes. The hard surface of the forks turns out to be another problem, as it damages the sensitive surface of the soft aluminum.

The CROC-Team helps: More safety and protection of the goods during the loading process

As a test, a pair of forks of a forklift truck is equipped with a 7 mm thick CROC coating in red with profile. In use, the effect is immediately apparent: the high slip resistance prevents the load from slipping, and the CROC coating also protects the surface of the aluminum. Thanks to its profiled surface, safe and highly noise-reduced transport is possible at all times, even in wet conditions. Since now it is clear: The other forklifts shall also be retrofitted with CROC coating with immediate effects.



CROC „red profiled“: More safety and protection of goods when loading

Mission accomplished – off to the next challenge!